

nRF5340

Engineering D

Errata

v1.0

Contents

1	nRF5340 Engineering D Errata	3
2	Revision history	4
3	New and inherited anomalies	5
3.1	[6] NVMC: Disabling instruction cache causes skip of next instruction	6
3.2	[43] QSPI: Reading QSPI registers after XIP might halt application CPU	6
3.3	[44] UARTE: TASKS_RESUME impacts UARTE	7
3.4	[47] TWIM: I2C timing spec is violated at 400 kHz	8
3.5	[55] RESET: Bits in RESETREAS are set when they should not be	8
3.6	[65] SAADC: Events are not generated when switching from scan mode to no-scan mode with BURST disabled	9
3.7	[70] NFCT: Event FIELDDETECTED may be generated too early	10
3.8	[71] NFCT: Frame delay timing is too short after SLP_REQ	11
3.9	[75] PWM: False SEQEND[0] and SEQEND[1] events are generated	11
3.10	[76] DPPI: Non-secure code can detect secure events	12
3.11	[87] RADIO: RSSI parameter adjustment	12
3.12	[99] QSPI: Mode 3 is not functional at 96 MHz	13
3.13	[112] I2S: 24-bit sample in a 32-bit half-frame is received incorrectly	13
3.14	[113] RADIO: Reading DTX in MODECNF0 gives incorrect value	14
3.15	[117] RADIO: Changing MODE requires additional configuration	14
3.16	[119] GPIO: Writes to LATCH register take several CPU cycles to take effect	15
3.17	[121] QSPI: Configuration of peripheral requires additional steps	16
3.18	[122] CTRL-AP: Successive triggering of CTRLAP.ERASEALL has no effect	16
4	Fixed anomalies	18

1 nRF5340 Engineering D Errata

This Errata document contains anomalies for the nRF5340 chip, revision Engineering D (CLAA-DA0, QKAA-DB0).

The document indicates which anomalies are fixed, inherited, or new compared to revision [Engineering A](#).

2 Revision history

See the following list for an overview of changes from previous versions of this document.

Version	Date	Change
nRF5340 Engineering D v1.0	03.12.2020	<ul style="list-style-type: none">• Added: No. 6. "Disabling instruction cache causes skip of next instruction"• Added: No. 43. "Reading QSPI registers after XIP might halt application CPU"• Added: No. 44. "TASKS_RESUME impacts UARTE"• Added: No. 47. "I2C timing spec is violated at 400 kHz"• Added: No. 55. "Bits in RESETREAS are set when they should not be"• Added: No. 65. "Events are not generated when switching from scan mode to no-scan mode with BURST disabled"• Added: No. 70. "Event FIELDDETECTED may be generated too early"• Added: No. 71. "Frame delay timing is too short after SLP_REQ"• Added: No. 75. "False SEQEND[0] and SEQEND[1] events are generated"• Added: No. 76. "Non-secure code can detect secure events"• Added: No. 87. "RSSI parameter adjustment"• Added: No. 99. "Mode 3 is not functional at 96 MHz"• Added: No. 112. "24-bit sample in a 32-bit half-frame is received incorrectly"• Added: No. 113. "Reading DTX in MODECNF0 gives incorrect value"• Added: No. 117. "Changing MODE requires additional configuration"• Added: No. 119. "Writes to LATCH register take several CPU cycles to take effect"• Added: No. 121. "Configuration of peripheral requires additional steps"• Added: No. 122. "Successive triggering of CTRLAP.ERASEALL has no effect"

3 New and inherited anomalies

The following anomalies are present in revision Engineering D of the nRF5340 chip.

ID	Domain	Module	Description	New in Engineering D	Inherited from Engineering A
6	Network	NVMC	Disabling instruction cache causes skip of next instruction		X
43	Application	QSPI	Reading QSPI registers after XIP might halt application CPU		X
44	Application, Network	UARTE	TASKS_RESUME impacts UARTE		X
47	Application, Network	TWIM	I2C timing spec is violated at 400 kHz		X
55	Application, Network	RESET	Bits in RESETRAS are set when they should not be		X
65	Application	SAADC	Events are not generated when switching from scan mode to no-scan mode with BURST disabled		X
70	Application	NFCT	Event FIELDDETECTED may be generated too early		X
71	Application	NFCT	Frame delay timing is too short after SLP_REQ		X
75	Application	PWM	False SEQEND[0] and SEQEND[1] events are generated		X
76	Application	DPPI	Non-secure code can detect secure events		X
87	Network	RADIO	RSSI parameter adjustment		X
99	Application	QSPI	Mode 3 is not functional at 96 MHz	X	
112	Application	I2S	24-bit sample in a 32-bit half-frame is received incorrectly	X	
113	Network	RADIO	Reading DTX in MODECNF0 gives incorrect value		X
117	Network	RADIO	Changing MODE requires additional configuration		X
119	Network	GPIO	Writes to LATCH register take several CPU cycles to take effect		X
121	Application	QSPI	Configuration of peripheral requires additional steps	X	
122	Network	CTRL-AP	Successive triggering of CTRLAP.ERASEALL has no effect	X	

Table 1: New and inherited anomalies

3.1 [6] NVMC: Disabling instruction cache causes skip of next instruction

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Network

Symptoms

The CPU skips the first instruction after instruction cache is disabled.

Conditions

The code executes instructions to disable the instruction cache.

Consequences

The program does not execute as expected.

Workaround

Use the following function to disable instruction cache:

```
_attribute__((aligned(ICACHE_LINE_SIZE)))  
  
void icache_disable(void) {  
    int key = DisableInterrupts();  
    __ISB();  
    NRF_NVMC->ICACHECNF = 0;  
    __ISB();  
    EnableInterrupts(key);  
}
```

3.2 [43] QSPI: Reading QSPI registers after XIP might halt application CPU

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application

Symptoms

Application CPU halts.

Conditions

Init and start QSPI, use XIP, then write to or read any QSPI register starting from offset 0x600 and above.

Consequences

Application CPU halts.

Workaround

Trigger QSPI TASKS_ACTIVATE after XIP is used before accessing any QSPI register with an offset above 0x600.

3.3 [44] UARTE: TASKS_RESUME impacts UARTE

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application, Network

Symptoms

Issuing TASKS_RESUME results in bits being set in the UARTE ERRORSRC register after it is enabled, even when not started.

Conditions

The internal state of a disabled UARTE changes when any of the tasks TASKS_RESUME, TASKS_STARTRX, or TASKS_STARTTX is triggered. These tasks are shared by UARTE, TWIM, TWIS, and SPIM.

Consequences

UARTE starts transmitting immediately after being enabled.

Workaround

Depending on which UARTE instance is affected, apply the following steps before enabling UARTE.

- If TXENABLE reads '1', trigger TASKS_STOPTX.
- If RXENABLE reads '1':
 - Enable UARTE.
 - Trigger TASKS_STOPRX.
 - Wait until RXENABLE reads '0'.
 - Clear ERRORSRC register.

The exact address depends on the UARTE instance. See the following table.

UARTE Instance	RXENABLE	TXENABLE
UARTE0:NS	0x40008564	0x40008568
UARTE0:S	0x50008564	0x50008568
UARTE1:NS	0x40009564	0x40009568
UARTE1:S	0x50009564	0x50009568
UARTE2:NS	0x4000B564	0x4000B568
UARTE2:S	0x5000B564	0x5000B568
UARTE3:NS	0x4000C564	0x4000C568
UARTE3:S	0x5000C564	0x5000C568

Table 2: Register addresses

3.4 [47] TWIM: I2C timing spec is violated at 400 kHz

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application, Network

Symptoms

The low period of the SCL clock is too short to meet the I2C specification at 400 kHz. The actual low period of the SCL clock is 1.25 μ s while the I2C specification requires the SCL clock to have a minimum low period of 1.3 μ s.

Conditions

Using TWIM at 400 kHz.

Consequences

TWI communication might not work at 400 kHz with I2C compatible devices.

Workaround

If communication does not work at 400 kHz with an I2C compatible device that requires the SCL clock to have a minimum low period of 1.3 μ s, use 390 kHz instead of 400 kHz by writing 0x06200000 to the FREQUENCY register. With this setting, the SCL low period is greater than 1.3 μ s.

3.5 [55] RESET: Bits in RESETREAS are set when they should not be

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application, Network

Symptoms

After pin reset, RESETREAS bits other than RESETPIN might also be set.

Conditions

A pin reset has triggered.

Consequences

If the firmware evaluates RESETREAS, it might take the wrong action.

Workaround

When RESETREAS shows a pin reset (RESETPIN), ignore other reset reason bits.

Note: RESETREAS bits must be cleared between resets.

Apply the following code after any reset:

```

For Application:
if (NRF_RESET_S->RESETREAS & RESET_RESETREAS_RESETPIN_Msk)
{
    NRF_RESET_S->RESETREAS = ~RESET_RESETREAS_RESETPIN_Msk;
}
For Network:
if (NRF_RESET->RESETREAS & RESET_RESETREAS_RESETPIN_Msk)
{
    NRF_RESET->RESETREAS = ~RESET_RESETREAS_RESETPIN_Msk;
}

```

This workaround is implemented in MDK version 8.29.0 and later.

3.6 [65] SAADC: Events are not generated when switching from scan mode to no-scan mode with BURST disabled

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application

Symptoms

SAADC stops working.

Conditions

Switching from single channel to multiple channels when BURST is disabled and acquisition time less than 10 us.

Consequences

SAADC internally locks up and does not generate the expected events.

Workaround

Execute the following code before changing the channel configuration.

- Secure mode:

```
NRF_SAADC_S->TASKS_STOP = 1;
```

- Non-secure mode:

```
NRF_SAADC_NS->TASKS_STOP = 1;
```

3.7 [70] NFCT: Event FIELDDETECTED may be generated too early

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application

Symptoms

Reset of the operating state after FIELDLOST event. In some cases, communication with the peer device is not possible.

Conditions

Especially with stronger field strengths.

Consequences

Restart of transfer is required.

Workaround

On FIELDDETECTED event, wait 1 ms using timer before starting NFC communication with NRF_NFCT->TASKS_ACTIVATE.

This workaround is included in nrfx v2.0.0 and later.

3.8 [71] NFCT: Frame delay timing is too short after SLP_REQ

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application

Symptoms

Reader may not accept the response from the tag.

Conditions

The time between SLP_REQ and ALL_REQ sent by the Reader is shorter than the time configured in FRAMEDELAYMAX.

Consequences

The protocol timing is violated, and a Reader may not accept the response from the tag.

Workaround

Ensure that FRAMEDELAYMAX is set to the default value when the NFCT is in states IDLE or SLEEP_A. The workaround is included in nrfx v2.0.0 and later.

3.9 [75] PWM: False SEQEND[0] and SEQEND[1] events are generated

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application

Symptoms

False SEQEND[0] and SEQEND[1] events are generated.

Conditions

Any of the LOOPSDONE_SEQSTARTn shortcuts are enabled. LOOP register is nonzero and SEQ[1].CNT is set to 1.

Consequences

SEQEND[0] and SEQEND[1] events might falsely trigger other tasks if they are routed through the PPI.

Workaround

Avoid using the LOOPSDONE_SEQSTARTn shortcuts when the LOOP register is nonzero and SEQ[1].CNT is set to 1.

3.10 [76] DPPI: Non-secure code can detect secure events

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Application

Symptoms

Non-secure code is able to detect that a secure event has been published to a secure DPPI channel.

Conditions

In a non-secure DPPI channel group, SUBSCRIBE_CHG[n].EN or SUBSCRIBE_CHG[n].DIS is set up to be connected to a secure DPPI channel.

Consequences

Non-secure code can detect that a secure event has been published to a secure DPPI channel. The non-secure code cannot detect which event has been published.

Workaround

Perform one of the following:

- Avoid using DPPI in secure mode.
- Configure all channel groups (CHG[n]) to include at least one DPPI channel that is configured as secure. This makes the channel groups secure and blocks them from being used on the non-secure side.

Note: The non-secure domain can still use the DPPI tasks and events system, but it does not have any available channel groups.

3.11 [87] RADIO: RSSI parameter adjustment

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Network

Symptoms

RSSI varies with temperature and input power level.

Conditions

Always.

Consequences

RSSI parameter is not within specified accuracy.

Workaround

Add the following compensation to the RSSI sample value based on temperature measurement and RSSISAMPLE. The on-chip TEMP peripheral can be used to measure temperature.

```

compensated_rssi = (uint8_t)round(
    (float)((float)(1.56f * rssi_sample) + (float)(4.9e-5 * pow(rssi_sample, 3)) -
    (float)(9.9e-3 * pow(rssi_sample, 2)) - (0.05f * ((float)(temp)*0.25f)) - 7.2f));

```

where

temp

Temperature sample value as reported by register NRF_TEMP.TEMP in increments of 0.25.

drssi_sample

Sample value as reported by register NRF_RADIO.RSSISAMPLE.

3.12 [99] QSPI: Mode 3 is not functional at 96 MHz

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

Domains

Application

Symptoms

Mode 3 is not functional at 96 MHz.

Conditions

Always.

Consequences

Mode 3 can be used only from 6 to 48 MHz.

Workaround

Use speed between 6 and 48 MHz or use Mode 0 to have full speed range.

3.13 [112] I2S: 24-bit sample in a 32-bit half-frame is received incorrectly

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

Domains

Application

Symptoms

24-bit sample in a 32-bit half-frame is received incorrectly.

Conditions

CONFIG.SWIDTH is configured to 24BitIn32.

Consequences

24-bit sample in 32-bit word has incorrect data from bits 25-31.

Workaround

Leave the first 24 bits in 32-bit word as is. Replace the 8 MSB bits of the 32-bit word by sign-extending the 24th bit.

3.14 [113] RADIO: Reading DTX in MODECNF0 gives incorrect value

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Network

Symptoms

Reading DTX in MODECNF0 gives incorrect value.

Conditions

Always.

Consequences

Reading the MODECNF0.DTX field returns an incorrect value.

Workaround

Treat the MODECNF0.DTX field as write only.

3.15 [117] RADIO: Changing MODE requires additional configuration

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Network

Symptoms

Radio modulation index is lower than expected.

Conditions

Always.

Consequences

RADIO may fail qualification tests or have higher than expected packet loss. Measured modulation characteristics for Bluetooth and error vector magnitude for IEEE802.15.4 are affected.

Workaround

After writing the RADIO.MODE register, perform the following additional configuration steps.

- When RADIO.MODE is set to Nrf_2Mbit, Ble_2Mbit, or leee802154_250Kbit, use the following:

```
*((volatile uint32_t *)0x41008588) = *((volatile uint32_t *)0x01FF0084);
```

- When RADIO.MODE is set to any other mode, use the following:

```
*((volatile uint32_t *)0x41008588) = *((volatile uint32_t *)0x01FF0080);
```

3.16 [119] GPIO: Writes to LATCH register take several CPU cycles to take effect

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

It was inherited from the previous IC revision [Engineering A](#).

Domains

Network

Symptoms

A bit in the LATCH register reads '1' even after clearing it by writing '1'.

Conditions

Reading the LATCH register right after writing to it.

Consequences

Old value of the LATCH register is read.

Workaround

Have at least 4 CPU cycles of delay between the write and the subsequent read to the LATCH register. This can be achieved by having 4 dummy reads of the LATCH register.

3.17 [121] QSPI: Configuration of peripheral requires additional steps

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

Domains

Application

Symptoms

QSPI is unstable or not working at all.

Conditions

Always.

Consequences

QSPI does not work as expected.

Workaround

When configuring QSPI, ensure register IFTIMING.RXDELAY = 6 and perform the following additional configuration steps.

- For operation at 96 MHz, perform the following extra configuration step:

```
NRF_QSPI.IFCONFIG0 |= ((1<<16) | (1<<17));
```

- For operation between 6 and 48 MHz, use this configuration step:

```
NRF_QSPI.IFCONFIG0 &= ~(1<<17);  
NRF_QSPI.IFCONFIG0 |= (1<<16);
```

3.18 [122] CTRL-AP: Successive triggering of CTRLAP.ERASEALL has no effect

This anomaly applies to IC Rev. Engineering D, build codes CLAA-DA0, QKAA-DB0.

Domains

Network

Conditions

Triggering CTRLAP.ERASEALL more than once.

Consequences

Subsequent triggering of CTRLAP.ERASEALL has no effect.

Workaround

Triggering CTRLAP.ERASEALL multiple times requires a pin reset between each triggering of CTRLAP.ERASEALL.

4 Fixed anomalies

The anomalies listed in this table are no longer present in the current chip version.

For a detailed description of the fixed anomalies, see the [Errata for revision Engineering A](#).

ID	Domain	Module	Description
1	Application	REGULATORS	VREGH short circuit protection is not functional
2	Application	TAD	Accessing external QSPI memory without configuring QSPI makes application core unresponsive
3	Application	SAADC	VDDHDIV5 is not functional
4	Application	CLOCK	Changing application core frequency register HFCLKCTRL requires additional register initialization
5	Application	TAD	Trace is not functional when application core is running at 128 MHz
7	Application	USB	USB is not functional
8	Application	WDT	WDT1 is not functional
9	Application	TAD	TPIU is missing from ROM table
10	Network	CCM	Reading CNFPTR, INPTR, OUTPTR, and SCRATCHPTR pointers returns incorrect address
11	Network	ACL	Reading ACL[n].ADDR returns incorrect address
12	Application	QSPI	SCKFREQ is not functional at 96 MHz
13	Application, Network	GPIO	Bits in LATCH register are incorrectly set to 1
14	Network	TIMER	CC[6] and CC[7] are not functional
15	Application, Network	UARTE	Odd parity setting is not functional
16	Network	RADIO	POWER register is not functional
18	Application	I2S	32-bit sample widths and 8-bit sample in a 16-bit half-frame are not functional
19	Application	SPU	Flash memory space is divided into 32 regions of 32 KiB
20	Application, Network	RTC	TASKS_CAPTURE[n], SUBSCRIBE_CAPTURE[n], and SHORTS registers are not functional
21	Application, Network	TWIM	1000 kbps baud rate is not functional
22	Application	SPU	CPULOCK register is not functional
23	Application	SAADC	Events are not generated when switching from scan mode to no-scan mode with BURST enabled
26	Application, Network	CTRL-AP	APPROTECT.DISABLE and SECUREAPPROTECT.DISABLE registers are not functional

ID	Domain	Module	Description
27	Application, Network	CTRL-AP	STATUS register is not functional
28	Application, Network	TIMER	INTEN register is not functional
29	Network	SWI	SWIRQ is not functional
30	Network	RESET	LCTRLAP field in RESETREAS register is not functional
31		TAD	Multidrop serial wire debug is not functional
32	Network	GPIO	GPIO pins assigned to network core do not retain their state in System OFF mode
33	Application	CLOCK	LFRC frequency starts drifting even if calibration task is triggered
34	Network	CTRL-AP	Erase all is not functional with APPROTECT enabled
36	Application	I2S	Excessive power consumption after using I2S STOP task
42	Application	CLOCK	Reset value of HFCLKCTRL is invalid
45	Application	SPIM	Receive is not functional at 32 Mbps
46	Application	CLOCK	LFRC has higher current consumption
49	Application, Network	POWER	SLEEPENTER and SLEEPEXIT events are asserted after pin reset
50	Application	SPU	Arm TrustZone region numbers for FICR, UICR, CACHEINFO, and CACHEDATA are incorrect
51	Application	SPU	Accessing FICR, UICR, CACHEINFO, or CACHEDATA from non-secure state gives bus error
52	Application, Network	VMC	RAM block is not writable immediately on power-up
53	Application	REGULATORS	Current consumption in normal voltage mode is higher in System ON idle
54	Network	REGULATORS	Current consumption in normal voltage mode is higher in System ON idle and System OFF
57	Application	I2S	EVENTS_FRAMESTART and PUBLISH_FRAMESTART registers are not functional
58	Application	I2S	BYPASS in CONFIG.CLKCONFIG is not functional
59	Application	QDEC	QDEC0 is not functional
62	Application, Network	UICR	HFXOCNT register is not functional
64	Application	REGULATORS	VREGMAIN has invalid configuration when CPU is running
66	Application	GPIO	P1.PIN_CNF[2-3], P0.PIN_CNF[8-18] DRIVE cannot be set in some configurations
67		DEVICE	ESD HBM is less than 2 kV
69	Application	REGULATORS	VREGMAIN configuration is not retained in System OFF

ID	Domain	Module	Description
72	Application	REGULATORS	Current consumption in high voltage mode is higher in System ON idle and System OFF
73	Application, Network	TIMER	ONESHOTEN[n] registers are located at an incorrect address offset
74	Application, Network	TIMER	COMPARE[i]_STOP is located at an incorrect bit number in the SHORTS register
77		TAD	Debug power-up request is not acknowledged
79	Application	QDEC	QDEC1 is not functional
80	Application	PWM	PWM3 is not functional
81	Application	SPIM	SPIM2 and SPIM3 are not functional
82	Application	TWIM	TWIM2 and TWIM3 are not functional
83	Application	SPIS	SPIS2 and SPIS3 are not functional
84	Application	UARTE	UARTE2 and UARTE3 are not functional
85	Application	NVMC	Reading or executing from flash memory can lead to errors when scaling frequency
86	Application, Network	CLOCK	EVENTS_DONE is not functional
90	Application	GPIO	PIN_CNF[n] MCUSEL is reset by application core soft reset
91	Network	RADIO	Ramp-up is slower than specified
93	Network	NVMC	Writing to flash requires high voltage on VREGRADIO
95	Network	REGULATORS	VREGRADIO DC/DC can malfunction
97	Application, Network	UICR	ERASEPROTECT or APPROTECT is occasionally enabled or device startup may fail
105	Application	SPIM, SPIS, TWIM, TWIS, UARTE	Peripheral has higher than expected current consumption
106	Application	SPIM	SPIM4 is not functional with GPIO.PIN_CNF[n].MCUSEL configured as Peripheral
109	Application	GPIONTE	LATENCY register is not functional
110	Application	QSPI	QSPI is not functional with GPIO.PIN_CNF[n].MCUSEL configured as Peripheral
114	Network	CPU	Accessing application core flash causes processor to become unresponsive
115	Application	CRYPTOCELL, USB	Peripheral cannot do DMA transfers from flash when application core processor is sleeping
116	Network	RADIO	Device spurious emission during transmit is higher than expected

Table 3: Fixed anomalies